



Recall after internal quality check

03/11/2014 As a precautionary measure, Porsche is replacing the lock bracket on the front lid of 4428 two-door sports cars worldwide.

The recall is because for some vehicles of the 911 Carrera, Boxster and Cayman model series it is not possible to guarantee that the bracket meets the specifications in the long term. However, to date there have not been any incidents (such as unintentional opening of the front lid).

The problem was discovered during in-house quality checks and was immediately corrected. The owners of the precisely identified vehicles will be contacted directly by their responsible Porsche dealer. Customers should visit a workshop as soon as possible. No costs will be incurred and the appointment will take approximately half an hour.

Link Collection

Link to this article

<https://newsroom.porsche.com/en/products/recall-after-internal-quality-check-10755.html>

Media Package

<https://pmdb.porsche.de/newsroomzips/9a1458fd-ad8c-4990-9cea-3f71acb23c19.zip>